

FAST - [FLOOR WITH T CONNECTOR.wsp I]

File View Edit Tools Window Help

Drafts
 Pending
 Active
 Failed
 Saved

(6) window with pane and sealant and spacer and mask\$4
 (63) window with pane and sealant and spacer and tape
 (5) window with pane and sealant and spacer and tape and deposit
 (55) window with pane and spacer and tape and coating
 (47) window with pane and spacer and coating and spray\$3
 (6) window with pane and spacer and coating and spray\$3 and silane
 (4) window with pane and spacer and coating and spray\$3 and silane and epoxy
 (4171) glass and coating and spray\$3 and silane and epoxy
 (756) glass and mask\$4 and coating and spray\$3 and silane and epoxy
 (107) window and glass and mask\$4 and coating and spray\$3 and silane and epoxy
 (20) window and glass and mask\$4 and coating and spray\$3 and silane and epoxy and sealant
 (2) glazing and mask\$4 and spray\$3 and silane and epoxy and sealant
 (4) "5066260"
 (33) ("1256818" | "1562948" | "1843432" | "1847574" | "2004878" | "2639254" | "2819656" | "28...

Favorites
 Tagged (0)
 UDC
 Queue
 Trash

5066260

	U	+	Document ID	Issue Date	Pages	Title	Current OR	Current XRef	Retrieval Class	Inventor	S	G	P	3	4	5	6	7	8	9	0
1			US 6370829 B1	20020416		Window structure installed in building	52/202	427/154; 427/244;		Diamond, Jeffrey H.											
2			US 6289642 B1	20010918		Method and window structure in buildings for protecting glass pane	52/202	427/154; 427/244;		Diamond, Jeffrey H.											
3			US 5066260 A	19990202	8	Masked glazing panels	428/426	428/428;		Adams, Jr., Lawrence O. et											

File Open Save Print View Help

Ready

* 6,120,708

Stack Mat'l.

428/429 - Glass next to silane

81 - perimeter of sheet

410 - surface modified glass

428 - next to silicon layer

Coating Process

427/389.7 - resin on glass base

386 - epoxy containing

50/171.3 - glass w/treatment, liquid